

**Question:**

My C9 is coming up on 100K miles. Do I need to check valve lash?

**Daves's Answer:**

The C9 and all electronic 3100 series engines do not require a valve lash check/adjustment prior to 150K miles. The correct valve lash settings are: Intake  $.015 \pm .003$  and Exhaust  $.025 \pm .003$ . Correct torque of the adjustment nut is extremely important.